

**Tiffany, Bruce**

---

**From:** Stern, Jeff  
**Sent:** Thursday, June 15, 2006 10:16 AM  
**To:** Tiffany, Bruce  
**Subject:** RE: Pics

Just tributary to 1541. Not sure when Shaun gets back. (b) (6)

---

**From:** Tiffany, Bruce  
**Sent:** Thursday, June 15, 2006 10:11 AM  
**To:** Stern, Jeff  
**Subject:** RE: Pics

If you know which colors and which lines you want to identify I can work with Shaun O'Neal on revising the figure.

---

**From:** Stern, Jeff  
**Sent:** Thursday, June 15, 2006 9:35 AM  
**To:** Tiffany, Bruce; Renaud, Rick; Salazar, Raleigh  
**Subject:** RE: Pics

Looks really nice. Although more organic than oily. Can you develop another version of the map with the tributary drains colored differently and place the parcel boundaries on it? If not, I can get one of our GIS folks to do it.

---

**From:** Tiffany, Bruce  
**Sent:** Thursday, June 15, 2006 9:12 AM  
**To:** Renaud, Rick; Salazar, Raleigh; Stern, Jeff  
**Subject:** FW: Pics

Rick, Raleigh, and Jeff;

Here are some photos from the sampling at Vault 1541 (see attached figure for location). As you can see from the photos, there appear to be inputs that are not typical stormwater runoff. It may be difficult to observe from the photos, but there are bubbles on the surface of the floating layer, indicating that there may be an anaerobic process occurring.

Although we do not have analytical results back yet, we have sufficient information to know that further investigation is needed regarding the sources that are tributary to this vault.

Thanks,

Bruce

---

**From:** Heinz, Dana  
**Sent:** Wednesday, June 14, 2006 4:11 PM  
**To:** Himes, Tammy; Tiffany, Bruce  
**Subject:** Pics

Bruce and Tammy -

Here are the pictures taken 6/8/06 at site 1541.

6/15/2006

Pics. 0011, 0012, 0013 are of a storm drain in the center of the parking lot – we think is draining into the sample site?

Pic. 0013 is of the storm drain in reference to site 1541.

Thanks,

Dana

6/15/2006

KCSlip4 57085

SEA423389